

Annexure D

BUILDING SAFETY CERTIFICATE

No. 237

Dated: 25/03/2025

It is certified that the existing building **Baheti Bihani Nutan English School, Selu** (name of the building or premises) at **Survey no. 9/1 Nutan college road, near Jaykwadi Vasahat, Selu** (address) is having block(s)/Floor(s) as per details below:

Details of Block(s) in	Block	Block	Block	Block	Block	Block
school	(1)	(2)	(3)	(4)	(5)	(6)
No. of Floor(s) in the Block	G + 2	G + 1				

The building is owned/occupied by **Baheti Bihani Nutan English School, Selu** (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of Deputy Engineer **Mr. Mane B.S.** (Name of Department/ Govt.) 24/03/2025 (date of inspection) in the presence of **Mr. Deulgaonkar B.D.** (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from 2015 for a period of 15 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. The work has been completed to my best satisfaction.
2. The workmanship and all the materials have been used strictly in accordance with general and detailed satisfaction.
3. The building is structurally sound safe and hygienic.
4. Hence it is fit for use how with Baheti Bihani Nutan English School, Selu is running.

Issued on 25/03/2025 at Selu Dist. Parbhani by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : _____

Name : **Mr. Mane B. S.**

Designation : **Sub Divisional Engineer
Deputy Engineer,
Public Works Sub-Division,
SAHU Office Parbhani**

Name & Address of Department Office
Deputy Engineer, P.W. Sub Division, Near
Railway Station, Selu Tq. Selu Dist. Parbhani
(431503)